


भवन सुरक्षा प्रमाण-पत्र

प्रमाणित किया जाता है कि अधोहस्ताक्षरकर्ता द्वारा दिनांक 03/02/2020 को ब्ल्यू माउण्ट इन्टरनेशनल सैकेन्डरी स्कूल गांव 10 बीएलएम-ए बिलोचिया तहसील श्रीविजयनगर के भवन का विजुअल निरीक्षण किया गया। नीचे वर्णित शर्तों एवं प्रस्तुत नक्शे व शपथ पत्र के आधार पर भवन को सुरक्षित घोषित किया जाता है। यह प्रमाण पत्र आज दिनांक 03/02/2020 को मेरे द्वारा जारी किया गया।

शर्तें

1. प्रमाण -पत्र की जारी अवधि में इस कार्यालय की बिना अनुमति के कोई निर्माण कार्य नहीं करवाया जाये।
2. बिजली फिटिंग व पखों के हुकों की समय समय पर जांच करवाई जावें।
3. यह प्रमाण पत्र केवल सिविल कार्य हेतु है, विद्युत कार्य इसमें शामिल नहीं है।
4. बरसात के मौसम से पहले छतों की सफाई आवश्यक रूप से करवाएं।
5. उक्त अनुपालना के अभाव में प्रमाण पत्र स्वतः निरस्त हो जावेगा।





(प्रदीप कुमार)सहायक अभियन्ता
सा.नि.वि. उपखण्ड श्रीविजयनगर

BLUE MOUNT INTERNATIONAL SEC. SCHOOL

VILLAGE 10 - B.I.M.

SRI VIJAY NAGAR


GROUND FLOOR PLAN




स्वायत्क अभियन्ता
श्री विजयनगर


BLUE MOUNT INTERNATIONAL SEC. SCHOOL
VILLAGE 10 - B.L.M.
SRI VIJAY NAGAR

FIRST FLOOR PLAN



FIRST FLOOR





 श्री विजय नगर
 शासक अभियन्ता
 श्री विं उय

BLUE MOUNT INTERNATIONAL SEC. SCHOOL


VILLAGE 10 - B.L.M.

SRI VIJAY NAGAR

SECOND FLOOR PLAN



LOCATION PLAN OF SCHOOL BUILDING



Bm
सहायक अभियन्ता
सा० वि० वि० उप खण्ड
श्री विजयनगर